

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Date of Examination: 02/13/07 Shift: Day Section or Area Examined: West Mains 003 Section

Violations and Other Hazardous Conditions Observed and Reported

Location	Violations or Hazardous Conditions	Action Taken
1. #1 face inby LOC	Entry too wide	Corrected
2. #3 outby LOC	Outby corner – 6 roof bolts sheared off	Corrected
3. 2 crosscut outby #2 face	Exposed electrical wiring on pump	Corrected
4. Tailpiece	Coal spillage around tail roller and guard missing	Corrected
5. Battery charging station	Fire extinguisher missing	Corrected
6. SCSR storage area	Need 2 additional SCSRs	Corrected

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. #5 face	7:30 am	0	6. #5 face	11:30 am	0
2. #4 face	7:45 am	.3	7. #4 face	11:45 am	.3
3. #3 face	7:50 am	.1	8. #3 face	11:50 am	.1
4. #02 face	7:55 am	.2	9. #02 face	11:55 am	.2
5. #01 face	8:00 am	.2	10. #01 face	12:00 pm	.2

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. #1 return	8:05 am	.2	4.		
2. #1 return	12:05 pm	.2	5.		
3.			6.		

Number of bolts tested 12 Number of bolts above range 0 Number of bolts below range 0

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken.

Remarks: _____