
Emergency and Unusual Situations
Account for all personnel
Ensure that employees know where to gather
Ensure employees know where emergency supply car is located
Ensure employees know their assigned job duties in case of emergency
Ensure communications
Notify Surface personnel and responsible person designated by the operator
Provide accurate information as to the location and what the emergency is
Request assistance if needed
Request transportation if necessary
Make sure that all SCSRs are gathered and available
Assess situation
Don't minimize possible seriousness of situation
Remove all personnel out by affected areas
Direct workforce at site
Instruct all employees to do a personal assessment for hazards as they approach a problem. Stop, Look, Analyze, Manage
Fire/Explosion
Refer to written firefighting plan
"First few minutes are the most critical"
Prepare to evacuate
Don't minimize possible seriousness of the situation
Make sure all SCSRs are together
Make sure the miners know escape routes
Prepare to barricade, if necessary
Know where emergency supply car is located
Inundations (water, gas)
Account for all persons
Hit emergency stop on power center
Withdraw to a safe location
Ventilate area (in case of gas) if possible
Refer to escapeway and evacuation plan
Serious Injury
Make sure area is safe
Provide first aid
Arrange for immediate transportation
Request ambulance
Request MET/backup
Communications with surface and request ambulance and backup
Roof falls (unintentional)
Account for all persons
Check for methane gas
If gas is detected, hit emergency stop on power center (see gas inundation procedures)
See gas inundation procedures
Danger off all approaches
Prepare to support area
Refer to unintentional roof fall plan roof falls related to anchorage, and or support
Report to mine management immediately